


INSTRUCTIONS FOR WIRING SHAPER
CONTROL TO MOTOR
(D.C. & 1-PH. A.C.)

[illegible]